
STRAIGHT GRAIN
5012 Jacket
UPPER_SLEEVE
Fabric type TOP_FABRIC, Piece qty =(1,1)
LEKO CAD
5012 Jacket
LOWER_SLEEVE
Fabric type TOP_FABRIC, Piece qty =(1,1)
STRAIGHT GRAIN


Fabric type LINING_FABRIC, Piece qty =(2,2)
-STRAIGHT GRAIN-
POCKET LINING
5012 Jacket
x
-STRAIGHT GRAIN-
5012 Jacket
UPPER_SLEEVE_LINING
Fabric type LINING_FABRIC, Piece qty =(1,1)
x


STRAIGHT GRAIN
5012 Jacket


FRONT_PART
Fabric type TOP_FABRIC, Piece qty =(1,1)
STRAIGHT G
5012 Jacket
LOWER_SLEEVE_LINING
Fabric type LINING_FABRIC, Piece qty =(1,1)
STRAIGHT GRAIN
STRAI


RAIN—
5012 Jacket
BACK_PART
Fabric type TOP_FABRIC, Piece qty =(1,1)




5012 Jacket
GHT GRAIN—
SIDE_FRONT_PART
Fabric type TOP_FABRIC, Piece qty =(1,1)
LEKO CAD


5012 Jacket
SIDE_BACK_PART
Fabric type TOP_FABRIC,
—STRAIGHT GRAI
LEKO CAD


GRAIN
5012 Jacket
CENTER_BACK_PART_LINING
Fabric type LINING_FABRIC, Piece qty =(1,1)
x
Piece qty =(1,1)
STRAIGHT


STRAIGHT GRAIN
GRAIN
STRAI

5012 Jacket
FRONT_FACING
Fabric type FUSIBLE_INTERFACING_TOP, Piece qty =(1,1)
LEKO CAD

5012 Jacket
CENTER_FRONT_PART_LINING
Fabric type LINING_FABRIC, Piece qty =(1,1)
LEKO CAD


5012 Jacket
SIDE_BACK_PART_LINING
Fabric type LINING_FABRIC, Piece qty =(1,1)
LEKO CAD
GHT GRAIN-
5012 Jacket
SIDE_FRONT_PART_LINING
Fabric type LINING_FABRIC, Piece qty
LEKO CAD
-STRAI GRAIN-
-STRAIGHT GRAIN-
5012 Jacket
LOWER_COLLAR
Fabric type TOP_FABRIC, Piece qty =(1,0)
LEKO CAD
-STRAIGHT GRAIN-
5012 Jacket
OUTER_COLLAR
Fabric type FUSIBLE_INTERFACING_TOP, Piece qty =(1,0)
LEKO CAD
-STRAIGHT GRAIN-
5012 Jacket
NECKLINE_FACING
Fabric type TOP_FABRIC, Piece qty =(1,0)